

United States Steel Corporation Clainton Works 400 State Street Clainton, PA 15025

## RECEIVED

MAY 2 8 2010

May 18, 2010

SAFIN

Mr. Ed Peresie Department of Air Quality Bureau of Air Pollution Control 301 Thirty-Ninth Street Pittsburgh, PA 15201

Mr. Steve Hepler
Department of Environmental Protection

U.S. Environmental Protection Agency Region III Air, Radiation & Toxics Division 1650 Arch Street Philadelphia, PA 19103-2029 ATTN: James W. Hagedorn (3AT23)

Mr. Steve Hepler
Department of Environmental Protection
Southwest Region
400 Waterfront Drive
Pittsburgh, PA 15222-4745

Department of Justice Environmental and Natural Resource Division Environmental Enforcement Section P.O. Box 7611 Ben Franklin Station Washington, D.C. 20044 ATTN: David Street, Esq.

Subject: USS Reference Number: 10-0196

ACHD Reference Number: 12541

600 Claus Plant USS Clairton Works

Gentlemen:

The attached form terminates the subject incident. Any questions concerning this matter should be referred to Coleen M. Davis at 412-233-1015.

Sincerely,

Mark G. Tabler Plant Manager Clairton Works

## NOTICE OF OUTAGE OF EQUIPMENT ARTICLE XXI - SECTION 2108.1

1. USS Reference Number: 10-0196 Termination

ACHD Reference Number: 12541

2. Date & Time of Outage: Date: 04/28/10 Time: 0800 hours

3. Company Name: U.S. Steel Corporation - USS Clairton Works

- 4. Specific Equipment Involved or Affected: 600 Claus Plant
- 5. BAPC Permit Number (if applicable):
- 6. Location: Clairton, PA
- 7. Nature and cause of breakdown: During an approximate 2 - 3 week period, the 600 Claus Plant will be unavailable for service to perform general maintenance.

The 600 Claus Unit is a redundant piece of equipment. processing for sulfur removal was handed off to the 400 Claus Unit. Sulfur Plant performance will not be affected. Sulfur emissions will not increase.

- 8. Identification of Emissions:
  - A. Type(s) (CO, NOX, SO2, Particulates, Hydrocarbons, etc.) The 400 Claus Plant will carry the full acid gas flow to the plant. No environmental impact is expected.
  - B. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). N/A No environmental impact is expected.
  - C. Amount of each type emitted (or likely to be emitted). N/A
- Measures taken (or to be taken) to minimize length of breakdown 9. and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so). Personnel, materials and equipment were on site prior to the start of the outage. The 400 Claus Plant carried the full acid gas flow to the plant.
- Facility back in operation Date: 05/16/10 Time: 0800 hours 10.

Signature (Clesom backs Date 5-19-10 Coleen M. Davis

Senior Environmental Control Engineer Phone: 412-233-1015